

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* ST02506NY

*This certificate issued to* BaySys Technologies, LLC  
24233 Lankford Highway  
Accomac, VA 23301

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

*Original Product - Type Certificate Number:* A16WE  
*Make:* Boeing  
*Model:* 737-300

*Description of Type Design Change:*

Installation of Interior Modifications in accordance with BaySys Technologies, LLC, Master Data List 8145-MDL, Revision E, dated December 21, 2007.

*Limitations and Conditions:*

1. BaySys Technologies, LLC, Airplane Flight Manual Supplement Document No. 8145-AFMS, Revision D, FAA approved February 06, 2008, is required for this installation.
2. The following BaySys Technologies, LLC., Maintenance Instructions or later FAA accepted revisions are required for this modification:
  - a. Instructions for Continued Airworthiness, Document No. 8145-ICAW, Revision E, dated November 20, 2007.
  - b. Maintenance Manual Supplement, Document No. 8145-MMS, Revision B, dated November 20, 2007.

(See Continuation Sheet 2)

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* July 17, 2007

*Date reissued:*

*Date of issuance:* February 06, 2008

*Date amended:*



*By direction of the Administrator*

*Ken Bowley*  
\_\_\_\_\_  
(Signature)  
For Anthony Socias  
Manager  
New York Aircraft Certification Office

\_\_\_\_\_  
(Title)